

ATTACHMENT A

TICK FIRE DESCRIPTION OF BURN AND POTENTIAL SEDIMENT IMPACT

Fire Name: Tick Fire
Date of Fire: October 24 to October 31, 2019
Burned Area: 4,615 acres
Location: Santa Clarita and Canyon Country area.

Vegetation Types before Burn

California montane chaparral and oak woodlands.

Fire History

There have been many fires that have burned within the perimeter of the Tick Fire, but the latest significant fire was the Freeway Fire No. 2 in 1995. Other fires older than 1995 are not shown on the Tick Fire History Map.

Summary of Potential Postfire Debris Flow Impacts

The Tick Fire burned area is divided into 300 subareas and is located in Debris Production Area zones 8 and 9. The debris production volumes noted in the Postfire Debris Flow Hazards Map are those resulting from a moderate to severe storm event. Parts of Tick Canyon Road, Sunrose Place, Wistaria Valley Road, and Doug Road in the City of Santa Clarita may be inaccessible due to flooding and sediment deposits during storm events. Below is a list of debris retaining inlets potentially impacted.

Debris Retaining Inlets

Name	City
Bayberry - PD 2227	Santa Clarita
Dana Court - PD 2516	Santa Clarita
Doug - PD 1624	Santa Clarita
Gary Place - MTD 1684	Santa Clarita
Jasmine - PD 2227	Santa Clarita
Kristine Drive - MTD 1684	Santa Clarita
Leigh Court - MTD 1684	Santa Clarita
Mammoth No. 1 - PD 2292	Santa Clarita
Mammoth Colorado No. 2 - PD 2292	Santa Clarita
Megan Drive - MTD 1684	Santa Clarita
Palomino No. 1 - PD 1975	Santa Clarita
Palomino No. 2 - PD 1975	Santa Clarita
Poppy 1 - PD 1815	Santa Clarita
Poppy 2 - PD 1815	Santa Clarita

Poppy Inlet - PD 1624	Santa Clarita
Quinn Drive - PD 2516	Santa Clarita
Ryan Lane No. 1 - PD 2516	Santa Clarita
Ryan Lane No. 2 - PD 2516	Santa Clarita
Shannon Court - PD 2516	Santa Clarita
Silver Saddles - PD 1975	Santa Clarita
Sturgeon Lane - MTD 1684	Santa Clarita
Sunrose - PD 2227	Santa Clarita
Tulipland - PD 1624	Santa Clarita
Wistaria - PD 1624	Santa Clarita

Evacuations

Evacuations of 99 potentially impacted properties in the City of Santa Clarita and Canyon Country area were under the purview of the Los Angeles County Sheriff's Department and Los Angeles County Fire Department otherwise referred to as Unified Command.

Engineering Advice

Public Works reviewed and surveyed potential impacts to 245 residences below the burned canyons and hillsides of the City of Santa Clarita and Canyon Country area of Unincorporated Los Angeles County. Postburn mudflow engineering advice was provided to 67 residents, which 18 were written and 49 were verbal.

P:\WRD\POSTFIRE DRAINAGE\FIRE\2019 FIRES\TICK FIRE\BAR\ATTACH A - DESCRIPT OF BURN & POTENTIAL SEDIMENT IMPACTS.DOCX